ControlLogix Digital I/O Modules

Before You Begin

IMPORTANT	**Do not backflash your module's firmware from firmware revision 3.*x* to 2.*x*.** Attempting to backflash or downgrade a module's firmware from 3.*x* to 2.*x* will irreversibly damage the module.
	You must return modules damaged by an attempt to backflash to firmware 2.*x* to Rockwell Automation.

In addition, attempting to upgrade a 2.*x* module to 3.*x* results in a ControlFlash error dialog. Upgrading a module's 2.*x* firmware to 3.*x* firmware is not supported.

About This Publication

This publication is for use with all 1756 Digital I/O modules. It contains important information about module revisions and their corresponding firmware.